

FIG. 1




FIG.2

IBM IntelliStation M Pro (Type 6849) -
Audio driver setup does not run in Finnish Windows 2000



Symptom

If an attempt is made to execute the audio driver setup from the C:\IBMTTOOLS\DRIVERS\AUDIO\ADI directory, the setup window flashes briefly and does not install the driver. This affects IBM IntelliStation M Pro (Type 6849) computers running under Microsoft Windows 2000 when on-board audio is enabled.

Affected countries

Finland

Workaround

Install the audio driver using an INF install. The steps are as follows:

1. In the C:\IBMTTOOLS\DRIVERS\AUDIO\ADIW2K directory of the pre-installed software, locate files : "smwdm.sys", "smwdm.inf", "smx.cat" (for signed drivers)
 2. Click Start. Click Settings. Click Control Panel, then double click the System icon
-

FIG. 3




FIG. 4

Summary	Location	OS	Model
[1] This audio driver package updates the sound feature in the ThinkPad system... Not all ThinkPad systems were shipped with the audio software...	Worldwide	Windows NT 4.0, Windows 95	600E, 600X, A30, T20
[2] Audio drivers have been updated to correct problems encountered... Download audio driver updates...	Worldwide	Windows XP	all
[3] This package provides the audio driver software... enables or updates audio function...	Australia	Windows 98/ME/2000	iSeries 1200
[4] ...			

FIG. 5

Location	Worldwide	Worldwide	Australia
Model	TP 600E, TP 600X, TP A30, TP T20	All ThinkPads	iSeries 1200
OS	Win 95	[1]	[3]
Win 98	[1]	[2]	[3]
Win 2000	[1]	[2]	[3]
Win ME	[1]	[2]	[3]
Win NT 4.0	[1]	[2]	[3]
Win XP	[1]	[2]	[3]

FIG. 6




FIG. 7




FIG. 8